

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2022

Submitted Date:

02/24/2022

Document Number:

688312247**FIELD INSPECTION FORM**Loc ID 472938 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Civitas		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
473326	WELL	DG	09/17/2021		005-07474	Sunset 4-65 21-22 2AH	WO
473327	WELL	DG	09/14/2021		005-07475	Sunset 4-65 21-22 2BH	WO

General Comment:[Frac Inspection](#)[Tank and container labels absent. Tank berm liners not maintained.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Minion Tanks, chemical totes, green frac tank and blue frac tank not labeled (see attached photos). Frac is almost done. Inspector talked with onsite personnel.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/28/2022

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	OTHER	OTHER		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other		Walls Insufficient		
Comment:	Green and blue frac tanks have liner inadequately installed (see attached photos). Inspector talked with onsite personel who were sending someone out to fix liner.			
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure.			Date: 03/25/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 473326 Type: WELL API Number: 005-07474 Status: DG Insp. Status: WO**Well Stimulation**Stimulation Company: Liberty Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:Maximum Casing Recorded: 8555 PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) 4660Bradenhead Psi: 0

Frac Flow Back: Fluid: _____ Gas: _____

Comment: Max BH 10982 psi
Stage 26

Corrective Action: _____

Date: _____

Facility ID: 473327 Type: WELL API Number: 005-07475 Status: DG Insp. Status: WO**Well Stimulation**Stimulation Company: Liberty Stimulation Type: HYDRAULIC FRAC

Other: _____

Observation:Maximum Casing Recorded: 8342 PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) 4987Bradenhead Psi: 0

Frac Flow Back: Fluid: _____ Gas: _____

Comment: Max BH 11274 psi
Stage 38

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402966247	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5674171
688312249	Crestone Sunset 4-65 21-22 2AH 2BH fracs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5674169