

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2022

Submitted Date:

03/05/2022

Document Number:

699602841

FIELD INSPECTION FORMLoc ID 323450 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245251	WELL	SI	03/01/2017	GW	123-13046	ROTH 12-30	PA

General Comment:

This is a PLUGGED & ABANDONED WELL / CEMENTING inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Plugging Operations / Cementing. Intermediate plugs, cementing.
 Battery: Inactive | Shut-down.
 Inactive Battery SE corner GPS coordinates: 40.455144 / -104.600555

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 245251 Type: WELL API Number: 123-13046 Status: SI Insp. Status: PA

CementCement ContractorContractor Name: Axis Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 3537'Cement Volume (sx): 40 sxsGood Return During Job: YESCement Type: Class "G" 15.8#Comment:

Workover Contractor: Axis Energy Services. Rig #714.

Cementing Contractor: Axis Energy Services.

Reference:

Form 6N on file. Notice of Intent to Abandon date: 01/26/2022. Approved.

Form 42 on file. Notice of MIRU.

Start Date: 03/01/2022. Approved.

Form 42 on file. Notice of Plugging Operations.

Start Date: 03/01/2022. Approved.

Form 17 Bradenhead Test on file. Date: 03/03/2022. Approved.

Intermediate plugs. Cementing.

CREW TO LOCATION.

IWP: 450 PSI / 0 PSI

HELD PJSM. CHECKED PSI, BLED OFF QUICK RU WL, RIH W/ RBL TO 4,000' AND

LOGGED TO SURFACE,

SENT RBL TO OFFICE FOR APPROVAL, RIH W/ PERF GUN AND SHOT@3,587',

SHOT SECOND HOLES@

3,487', SET A CICR @3,537', RD WL. RIH W/ STINGER ON WS AND STUNG INTO

CICR. RU CEMENTERS,

PUMPED 10 BBL CHEM WASH, 5 BBL MUD FLUSH, 40 SX OF CLASS G 15.8 PPG,

1.15 YLDAND LEFT LAST

5 SX ON TOP OF CICR, RD CEMENTERS. PU TO 2,800' REV CIRC. POOH.

MECHANIC AND CREW

INSPECTED DRAWWORKS. SECURE WELL AND SDFN.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 03/04/2022 at approximately 14:47 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROTH-66N64W /30NWSW Location ID: 323450 Well Name(s): Roth 12-30. API: 05-123-13046. Location County: Weld County, Colorado Weather: Partly Sunny, wet w/ mud from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing. Intermediate plugs, cementing. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.455144 / -104.600555</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/05/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602842	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5682652