

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2022

Submitted Date:

02/28/2022

Document Number:

697601797**FIELD INSPECTION FORM**Loc ID 336263 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Deranleau, Greg		greg.deranleau@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Inspections, Oxy		COGCCInspections@Oxy.co m	All Anadarko Inspections
Axelson, John		john.axelson@state.co.us	

General Comment:

Inspection of area near to a reported removed flowline listed as Kerr McGee operator feature 10517329-02 in COGCC records. Crew doing utility locate potholes related to development of area reported finding hydrocarbon impacted soils in contact with water near or in path of one or more flowlines. Pot holing crews sampled soil and submitted for laboratory analysis with lab results attached to this inspection. Photos of the site were from the development crew are included in the attached complaint document.

Other flowlines are known to be in proximity to the now reported removed flowline of Kerr McGee. Pinflags marking the existing flowline of second operator(KPK Facility 4 East Consolidation 1 line with photos of KPK marker signs attached) within 10-15 feet of previous operator flowline marker (HS Resources sign with photo attached). HS Resources well in area was tranferred to Kerr McGee in 2001 with report of removal by Kerr McGee of the former HS Resources flowline in 2019.

Both operators who have or had flowlines in close proximity to the site are receiving similar requirement to investigate and report under Rule 912.b. Investigation must be performed until source of hydrocarbon impacts to soil and groundwater are identified and at this point both operators are considered responsible parties.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: contractor for developer found hydrocarbon impacted soils in contact with groundwater near site of now removed flowline segment 10517329-02.

Corrective Action: investigate area of reported spill within 72 hours of this notification and follow spill reporting as outlined in rule 912 in particular with respect to Rule 912.b(1)F.

Date: 03/03/2022

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: Other

Comment: observation by crew potholing utility as part of development

Sample

Sample Type: SOIL GRAB

Time: _____ (MM/dd/yyyy hh:mm) GPS: Lat _____ Long _____

BTEX: _____ TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____

Dissolved Methane: _____ Composition: _____ Stable Isotopes: _____ 8260: _____

8270: _____ RCRA Metals: _____ 910-Metals: _____ PAH: _____

Other: _____

Comment: soil samples collected by crew employed by developer and samples submitted to laboratory for analysis

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402968179	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676329
697601800	overview aerial - with COGIS flowline location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676313
697601801	soil lab report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676314
697601802	complaint document	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676315
697601803	HS Resources line marker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676316
697601804	KPK Manifold COGCC facility 479311	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676317
697601805	KPK line marker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676318
697601806	KPK line marker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676319
697601807	Detailed aerial with possible spill area marked	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676320