

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2022

Submitted Date:

03/02/2022

Document Number:

701102799

**FIELD INSPECTION FORM**Loc ID 315226 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL &amp; GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

8 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Thompson, Bud		BLThomps@BLM.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230443	WELL	PR	11/08/2000	GW	103-08106	CONTINENTAL 3-17	PR

**General Comment:**

COGCC Routine Inspection Report Summary Location is within a Rule 1202.d Mule deer migration corridor and a Black bear area. A follow up to 12/22/2020 inspection 700404719, 7/27/2021 inspection 701101776

The following compliance issues are uncompleted:

- Meter last calibrated in 2019.
- No battery sign at tank battery.
- Label doesn't meet Rule 605.h. (missing information). No NFPA sticker, no operator name and no operator contact number.
- Sign is illegible. Sign is hung upside down. Sign was made for another well and has this wells information written over the old information. The Api # is not correct. Well name and legal description is illegible.
- Weeds cleared from location. Dead debris around equipment and tank.
- No braden head access. Surface casing open to atmosphere.
- No tank berm.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	CR 27 & CR 28			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign is illegible. Sign is hung upside down. Sign was made for another well and has this wells information written over the old information. The Api # is not correct. Well name and legal description is illegible.			
Corrective Action:	Install sign to comply with Rule 605.e.			Date: 08/30/2021
Type	TANK LABELS/PLACARDS			
Comment:	Label doesn't meet Rule 605.h. (missing information). No NFPA sticker, no operator name and no operator contact number.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 08/30/2021
Type	BATTERY			
Comment:	No battery sign at tank battery.			
Corrective Action:	Install sign to comply with Rule 605.e.			Date: 10/30/2021
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Weeds cleared from location. Dead debris around equipment and tank.			
Corrective Action:	Comply with Rule 606			Date: 03/19/2022
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	TANK BATTERY			
Comment:				
Corrective Action:				Date:
<b>Equipment:</b>				corrective date
Type: Bradenhead	#			
Comment:	No braden head access. Surface casing open to atmosphere			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)			Date: 08/05/2021
Type: Horizontal Heated Separator	# 1			

Comment:	Heat equipment disassembled from heated separator. Open access to wildlife.			
Corrective Action:	Cover open access to protect wild life.		Date:	04/02/2022
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Meter last calibrated in 2019.			
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date:	02/01/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	Open Top		,	
Comment:	Open top tank buried					
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm around tank.			
Corrective Action:	Install or maintain berm.			
			Date:	08/14/2021

**Venting:**

Yes/No		
Comment:	Surface casing open to atmosphere.	
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 230443 Type: WELL API Number: 103-08106 Status: PR Insp. Status: PR**Producing Well**Comment: Last production reported in database December 2021

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402970892	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5679448">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5679448</a>
701102800	Inspection 701102799 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5679440">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5679440</a>