

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2022

Submitted Date:

03/08/2022

Document Number:

701102821**FIELD INSPECTION FORM**Loc ID 315079 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230221	WELL	PR	03/01/2019	GW	103-07880	C & K 1-6	PR

General Comment:**COGCC Follow Up Inspection Report Summary**

Follow up to 07/27/2021 inspection # 701101781

- Well sign is illegible. No API # on well sign.
- Label has wrong operator name.
- No battery sign at tank battery.
- Unused equipment on location. Pump jack and production tank not in use.
- Unmarked deadmen and marker not brightly colored.
- Bradenhead access is not present.
- Tank berm is not complete.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Well sign is illegible. No API # on well sign.			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 11/04/2021
Type	TANK LABELS/PLACARDS			
Comment:	Label has wrong operator name.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 11/04/2021
Type	BATTERY			
Comment:	No battery sign at tank battery.			
Corrective Action:	Install sign to comply with Rule 605.e.			Date: 11/04/2021
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment on location. Pump jack and production tank not in use.			
Corrective Action:	Comply with Rule 606			Date: 08/20/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PIT			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Deadman # & Marked	# 3			corrective date
Comment:	Unmarked deadmen and marker not brightly colored.			
Corrective Action:	Mark all deadmen with bright color.			Date: 08/20/2021
Type: Bradenhead	#			
Comment:	Bradenhead access is not present.			

Corrective Action:	Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.	Date:	02/01/2021
--------------------	--	-------	------------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	240 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Berm is not complete.			
Corrective Action:	Repair or install berms or other secondary containment devices.			Date: 03/17/2021

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 230221	Type: WELL	API Number: 103-07880	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well Producing from annulus			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective

Date:

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: Partly Temperature: 21 (F)Assisting Staff: _____ Camera #: 2☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:10	AM	11:20	AM

Equipment
Other
Wellhead(s)

Comment: Survey well head and meter shed. No gas leaks observed.

Corrective

Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402976799	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5684979
701102824	Inspection 701102821 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5684976