

Collection Station 29,
facility ID 117365 and 117285
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel



Photo #1

Collection Station 29,
facility ID 117365 and 117285
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel



Photo #2

Inspection Photos
Collection Station 29,
facility ID 117365 and 117285
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel



Photo #3 Secondary containment area, of photo#2





Inspection Photos
Collection Station 29,
facility ID 117365 and 117285
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel

Photo #4 stormwater feature. It appeared the gate was closed. It was too muddy to walk down.





Inspection Photos
Collection Station 29,
facility ID 117365 and 117285
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel

Photo#5 close-up of photo #4

