

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2022

Submitted Date:

03/16/2022

Document Number:

699602917

FIELD INSPECTION FORM

Loc ID 302672 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 19 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299967	WELL	TA	12/01/2020	OW	123-29579	WALCKER 12-23	TA

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
(302672, 417667).
(Well(s): 2: Temporarily Abandoned | TA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Braided wire. Surrounded by earth berms.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		

Comment: Braided wire.			
Corrective Action:			Date:
Equipment:			corrective date
Type: Prime Mover	# 1		
Comment: Gas engine drives pumpjack. Shut-down.			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment: Gas Sales. Calibration card(s) indicates calibration within last year. Last calibration: 04/20/2021. Inactive, no production.			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment: Shut-down.			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: ECD scrubber.			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment: Crude storage vapor line combustor(s). Controls crude oil tanks vapors. Pilots: OFF. Shut-down.			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment: Wellhead: w/ Master & casing valves.			
Corrective Action:			Date:

Tanks and Berms:


Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment: Centralized Battery serves 2 Location IDs (302672, 417667).					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		
Comment:					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)	60 Bbls.				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks.					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.589135,-104.506863
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ produced H2O vaults.					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:



Inspected Facilities

Facility ID: 299967 Type: WELL API Number: 123-29579 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.

Form 4 on file. TA date: 08/31/2020.
Form 21 MIT on file. Date: 09/01/2020.
Form 42 MIT Notice on file. Date: 08/31/2020.
Blue TA tag posted.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 05/27/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 03/15/2022 at approximately 15:50 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WALCKER /12-23 Location ID: 302672 Well Name(s): Walcker 12-23. API: 05-123-29579. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (302672, 417667). (Well(s): 2: Temporarily Abandoned TA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602918	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5696167