

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2022

Submitted Date:

03/17/2022

Document Number:

694500397

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
 Name of Operator: CHEVRON USA INC  
 Address: 100 CHEVRON ROAD  
 City: RANGELY State: CO Zip: 81648

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jackson, Spencer	972-965-5580	spencer.Jackson@scoutep.com	
Paterson, Chris	970-620-3456	chris.patterson@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102575	PIT	AC			-	RANGLEY WEBER STATION 3	EI

**General Comment:**

On 3/8/2021 COGCC staff, Kris Neidel inspected Collection Station 3. Weather was; 32 degrees, melted snow and very muddy. Due to the mud, the focus of the inspection was related to pits, Facility 102575. The Pit was observed, some holes and gaps in the netting/Fence combo were observed. . See attached photos.

**Inspected Facilities**

Facility ID: 102575 Type: PIT API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Emergency      Lined: YES      Pit ID: 102575      Lat: 40.144950      Long: -108.924902

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: Other      Liner Condition: \_\_\_\_\_

Comment: liner type and Condition is unknown. looking at it can not make this determination.

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Netting/Fence com      Fencing Condition: \_\_\_\_\_

Comment: netting has some gaps and holes.

Corrective Action: repair gaps and holes, see attached photos.

Date: 03/22/2022

**Netting:**

Netting Type: Fence/Net Combo      Netting Condition: Good

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: YES      Oil Accumulation: YES      2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
694500398	photo	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5696893">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5696893</a>