

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



Photo #6175 from entrance to location.



Photo #6176 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



Photo #6177 from entrance to location.



Photo #6178 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



Photo #6179 Multiple places with debris on location.



Photo #6190 Multiple places with debris on location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6182 Multiple places with trash on location.**



**Photo #6186 Multiple places with trash on location.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6187 Multiple places with trash on location.**



**Photo #6189 Multiple places with trash on location.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6185** Multiple places with equipment and stored supplies on location.



**Photo #6192** Multiple places with equipment and stored supplies on location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



Photo #6003 from inspection #699804184 conducted on 2/24/22.



Photo #6004 from inspection #699804184 conducted on 2/24/22.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6184 Tanks missing required information.**



**Photo #6188 Material handling and spill prevention BMP's have not been implemented.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6204 . Insufficient maintenance of material handling and spill prevention BMP's. Containment full of an unknown fluid.**



**Photo #6202 Insufficient materials covering and BMP implementation.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6180 Location lacks stabilization.**



**Photo #6183 Location lacks stabilization.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6193 Rill erosion occurring on location.**



**Photo #6194 Sediment trap insufficient.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6195 Sediment trap insufficient.**



**Photo #6196 sediment trap insufficient.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW

Location ID: 335299



**Photo #6197 Sediment migration continued. Trash has been transported off location.**



**Photo #6199 Insufficient tracking BMP at entrance to location.**



## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NESW**

**Location ID: 335299**



**Photo #6205 Insufficient tracking BMP at entrance to location.**