

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO /PA 443-34

Location ID: 428684



Photo #6227 Pipeline right of way.



Photo #6228 Pipeline right of way.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO /PA 443-34

Location ID: 428684



Photo #6233 Insufficient materials covering and BMP implementation.



Photo #6234 Insufficient materials covering and BMP implementation

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO /PA 443-34

Location ID: 428684



Photo #6235 Insufficient materials covering and BMP implementation.



Photo #6236 Pipeline right of way lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO /PA 443-34

Location ID: 428684



Photo #6237 Insufficient tracking BMP's from pipe line right of way to access road.



Photo #6240 Drainage blocked by dirt pile.