

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2022

Submitted Date:

03/15/2022

Document Number:

699804254

FIELD INSPECTION FORM

Loc ID 334702 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294285	WELL	PR	08/30/2008	GW	045-15361	SPECIALTY RESTAURANTS SG 312-26	PR
294286	WELL	PR	07/31/2008	GW	045-15362	SPECIALTY RESTAURANTS SG 511-26	PR
294287	WELL	PR	08/20/2008	GW	045-15363	SPECIALTY RESTAURANTS SG 412-26	PR
294288	WELL	PR	07/31/2008	GW	045-15364	SPECIALTY RESTAURANTS SG 411-26	PR
294290	WELL	PR	08/30/2008	GW	045-15365	SPECIALTY RESTAURANTS SG 311-26	PR
294292	WELL	PR	01/11/2008	GW	045-15366	SPECIALTY RESTAURANTS SG 11-26	PR
294294	WELL	PR	08/30/2008	GW	045-15367	SPECIALTY RESTAURANTS SG 512-26	PR
294296	WELL	PR	07/31/2008	GW	045-15368	SPECIALTY RESTAURANTS SG 12-26	PR

General Comment:

COGCC Inspection Report Summary

On Monday 3/14/22 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS67S96W /26SWNW. Location #334702 in Garfield County Colorado.

Refer to document #699803643 inspection conducted on 9/20/21.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 3/29/22.

Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Taylor plugs located on braden head. All braden head valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	294285	Type:	WELL	API Number:	045-15361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294286	Type:	WELL	API Number:	045-15362	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294287	Type:	WELL	API Number:	045-15363	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294288	Type:	WELL	API Number:	045-15364	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294290	Type:	WELL	API Number:	045-15365	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294292	Type:	WELL	API Number:	045-15366	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294294	Type:	WELL	API Number:	045-15367	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294296	Type:	WELL	API Number:	045-15368	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Sediment Traps						
		Berms				
		Compaction				
Berms						
Compaction	Fail					Location lacks stabilization
Gravel	Fail					Gravel insufficient
		Ditches				
		Gravel				
Ditches						
Other	Fail					Insufficient tracking BMP at entrance to location.
		Sediment Traps				

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 03/29/2022

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	03/15/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402985211	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5694007
699804257	Photos for Insp. #699804254	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5694000