

# Inspection Photos

March 15, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 311695

Location Name: Gentry-66S92W /17SESE

Inspection Document #: 702800045

Garfield County, CO

SESE Section 17 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Gentry-66S92W /17SESE  
Location ID: 311695



**Photo 1.** Photo taken from the Location entrance facing northeast shows an overview of the Location.



Inspection Photos  
Location Name: Gentry-66S92W /17SESE  
Location ID: 311695



**Photo 2.** Photo taken from the north of the Location facing north shows undesirable plant species/weed debris accumulating in production areas.



**Photo 3.** Photo taken from the well equipment facing west shows undesirable plant species/weed debris accumulating in production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Number: 702800045

Inspection Photos  
Location Name: Gentry-66S92W /17SESE  
Location ID: 311695



**Photo 4.** Photo taken from the well equipment facing west shows BMPs to prevent wildlife access to the well cellars were missing or insufficient.



**Photo 5.** Refer to Photo 5 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800045

Inspection Photos  
Location Name: Gentry-66S92W /17SESE  
Location ID: 311695



**Photo 6.** Photo taken from the southeastern interim area of the Location facing northeast shows interim areas dominated by the annual undesirable plant species/weed, Kochia.



Inspection Photos  
Location Name: Gentry-66S92W /17SESE  
Location ID: 311695



**Photo 7.** Photo taken from the east of the Location facing west shows rutting occurring on the pad.



**Photo 8.** Photo taken from the east of the Location facing north shows rutting occurring on the pad.

