

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2022

Submitted Date:

03/22/2022

Document Number:

702400095**FIELD INSPECTION FORM**Loc ID 318399 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241226	WELL	TA	12/30/2019	OW	123-09014	1415 CORP UNIT F 1	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	UNUSED EQUIPMENT	
Comment:	concrete slab for pump jack, unused ancillary equipment.	
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements.	Date: 10/28/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:		
Type	OTHER	
Comment:	unused ancillary equipment has fabricated steel pipe and round stock	
Corrective Action:		Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	unused Electric panel, meter box and transformers		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 699304331 for information concerning well shared facilities and equipment				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241226 Type: WELL API Number: 123-09014 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: TA, Form 04 TA Doc # 401784269 5-16-2019. Well last produced March 2005. This well does have a MIT 12/12/2019. Well is due for another MIT or be produced before 12/12/2021. "Well was found in state of Temporary Abandonment."

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 01/25/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 3/22/2022 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Follow up inspection to Doc # 699304333</p> <p>Operator: KP Kauffman</p> <p>Location: 1415 Corp. Unit F #1</p> <p>API #05-123-09014</p> <p>County: Weld.</p> <p>While there, I observed a wellsite, TA at the time of inspection.</p> <p>During this inspection the following possible compliance issue has been addressed:</p> <p>606 housekeeping: weeds growing around WH and location have been cut.</p> <p>During this inspection the following possible compliance issues are now delinquent:</p> <p>606 housekeeping: Unused concrete slab where pump jack would be placed, unused transformers and meter box, CA date 10-28-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: cloudy, windy and cold.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	03/22/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400096	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701505