

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2022

Submitted Date:

03/22/2022

Document Number:

702400097**FIELD INSPECTION FORM**Loc ID 318238 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240940	WELL	TA	06/20/2019	OW	123-08728	1415 CORP. UNIT E 1	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused concrete slab where pump jack would be placed, unused transformers and meter box		
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements.	Date:	10/28/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	unused ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	meter box and transformers (unused)	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	appears to be plumbed to surface	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares containment with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.110570,-104.835850
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-09014
123-08728

**AirsID**

API Number	AirsID
------------	--------

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**Facility ID: 240940 Type: WELL API Number: 123-08728 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA, Form 04 TA Doc # 401982160 5-16-2019. Well last produced April 2006. This well does have a MIT 2/21/2019. Well was due for another MIT or produced before 2/21/2021 and is delinquent. "Well was found in state of Temporary Abandonment. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b."

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.

Date: 10/28/2021**BradenHead**Date of Last Brhd Test: 02/23/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: \_\_\_\_\_Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 3/22/2022 at approximately 1320 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Follow up inspection to Doc # 699304331.</p> <p>Operator: KP Kauffman</p> <p>Location: 1415 Corp. Unit E #1</p> <p>API #05-123-08728</p> <p>County: Weld.</p> <p>While there, I observed a wellsite and tank battery, TA at the time of inspection.</p> <p>During this inspection the following possible compliance issue has been addressed:</p> <p>606 housekeeping: weeds growing around WH concrete slab and ancillary equipment have been cut and removed.</p> <p>During this inspection the following possible compliance issues were observed and are delinquent:</p> <p>606 housekeeping: Unused concrete slab where pump jack would be placed, unused transformers and meter box, CA date 10-28-2021.</p> <p>417.c MIT(TA wells): Well is overdue for Mechanical Integrity Test. Most recent test was on 2-21-2019, CA date 10-28-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: cloudy and cold.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	03/22/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400098	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5701506</a>