

Inspection Photos  
UPRR 42 Pan Am D 2 battery  
Facility ID: 470886



Photo 1 – Battery sign. Impacted soil surrounding crude oil tank.



Photo 2 – Spill area on south side of produced water tank.

Inspection Photos  
UPRR 42 Pan Am D 2 battery  
Facility ID: 470886



Photo 3 – Spill source on east side of crude tank.



Photo 4 – Spill source on east side of crude tank.

Inspection Photos  
UPRR 42 Pan Am D 2 battery  
Facility ID: 470886



**Photo 5 – Spill area on south side of produced water tank.**



**Photo 6 – Spill area on south side of crude tank.  
Spill clean up in process.**

**Inspection Photos**  
**UPRR 42 Pan Am D 2 battery**  
**Facility ID: 470886**




**Photo 7 – Spill clean up in process. Impacted soil being cleaned up by shovels and placed into loader.**



**Photo 8 – Impacted soil loaded onto flat bed truck.**

Inspection Photos  
UPRR 42 Pan Am D 2 battery  
Facility ID: 470886



**Photo 9 – Active spill observed by COGCC inspector  
3/21/2022.**

**Photo 10 – Active spill observed by COGCC inspector  
3/21/2022 (video).**

**Inspection Photos**  
**UPRR 42 Pan Am D 2 battery**  
**Facility ID: 470886**



**Photo 11 – Oily soil on east side of crude tank documented in Inspection #699304532 on 11/23/21**