

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2022

Submitted Date:

03/17/2022

Document Number:

688801114

FIELD INSPECTION FORM

Loc ID 325233 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 18 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
		sjninspections@ikavenergy.com	All Inspections
Beebe, Sabre		sabre.beebe@ikavenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214367	WELL	PR	09/01/2019	GW	067-05777	PAN AMERICAN FEE A 1	EI
411831	WELL	PR	04/01/2020	GW	067-09713	PAN AMERICAN FEE C 2	EI
411832	WELL	PR	02/16/2011	GW	067-09714	PAN AMERICAN FEE C 4	EI
481775	SPILL OR RELEASE	AC	03/17/2022		-	Pan American Fee C 2 water line	EI

General Comment:

On March 16, 2022 SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Pan American Fee C #2. For the most recent field inspection report of this facility, please refer to document #693904233.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing signs near location entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Free standing signs near both PBVs labeled with contents, capacity, and NFPA placards.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Stock panel fencing around all production equipment on site.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing around A #1 well head.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Stock panel fencing around both pump jacks and well heads. Guard fencing present around both pump jacks.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stock panels around telemetry equipment.		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 3		corrective date
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2		
Comment:	Electrical supply equipment. Pump controller for C #2 is tagged out in response to Spill/Release Point ID #481775.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	A #1 well head.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:	C #4 and C #2 well heads. C #4 pump jack operating during this inspection. C #2 tagged out.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.093753,-107.708556
Comment:	Double walled steel PBV with vent stack.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment berm. Double walled steel PBV with vent stack.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.093787,-107.708291
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-05777
067-09714
067-09713

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		Date:	
Comment:			
Corrective Action:			Date:

Flaring:

Type		Date:	
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 214367 Type: WELL API Number: 067-05777 Status: PR Insp. Status: EI

Facility ID: 411831 Type: WELL API Number: 067-09713 Status: PR Insp. Status: EI

Facility ID: 411832 Type: WELL API Number: 067-09714 Status: PR Insp. Status: EI

Facility ID: 481775 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 6

Comment: Please see document #402986853 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 04/18/2022

Reportable: YES

GPS: Lat 37.093800

Long -107.708022

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: _____ Pit ID: 115638 Lat: 37.094949 Long: -107.706983

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: The status of Pit Facility ID #115638 has been changed to active and the coordinates have been updated to reflect the location of the PBV for the A #1.

Corrective Action:

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>On March 16, 2022 SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Pan American Fee C #2. For the most recent field inspection report of this facility, please refer to document #693904233. The purpose of this site visit was to document the conditions related to Spill/Release Point ID #481775. During this field inspection it was noted that the pump controller for the C #2 had been tagged out as a result of Spill/Release Point ID #481775. The C #4 pumping unit was operating during this inspection. There was an approximately 12" diameter hole where Spill/Release Point ID #481775 day lighted on the eastern edge of the location. Staining was visible from around the hole continuing along the access road.</p>	hughesjo	03/17/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402988179	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5697157
688801115	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5697153