

TEP  
RMV 116-33  
Location # 334780



location



location



TEP  
RMV 116-33  
Location # 334780



location



location



TEP  
RMV 116-33  
Location # 334780



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**



TEP  
RMV 116-33  
Location # 334780



**Lack of stabilization/compaction/erosion and sediment migration**



**Lack of stabilization/compaction**





TEP  
RMV 116-33  
Location # 334780



Labeling illegible



Lack of stabilization/compaction



TEP  
RMV 116-33  
Location # 334780



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**





TEP  
RMV 116-33  
Location # 334780



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**



TEP  
RMV 116-33  
Location # 334780



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**





TEP  
RMV 116-33  
Location # 334780



**Lack of BMP's**



**Lack of BMP's**





**TEP**  
**RMV 116-33**  
**Location # 334780**



**Lack of BMP's**



**Lack of stabilization/compaction**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources