

Inspection Photos
Location Name: Coyote Canyon 33-9 #20-3
API: 05-067-08485



Coyote Canyon 33-9 #20-3 well head and pump jack.



286 bbl. heated steel AST.

Inspection Photos

Location Name: Coyote Canyon 33-9 #20-3

API: 05-067-08485



Well head is wet and stained. Surrounding area is stained. Puddle of fluids present within wooden cellar.



Lube oil container appears to be leaking. Stand and soil beneath are wet and stained.

Inspection Photos
Location Name: Coyote Canyon 33-9 #20-3
API: 05-067-08485



Concrete pad is wet and stained beneath prime mover. Soil adjacent to prime mover is stained.



Coyote Canyon 33-9 #20-3 production equipment.