

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2022

Submitted Date:

03/21/2022

Document Number:

696304058

FIELD INSPECTION FORMLoc ID 430695 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430694	WELL	PR	03/17/2013	OW	123-36257	Razor 22-2712H	PR
435213	WELL	PR	09/01/2020	OW	123-38507	Razor 22D-2208B	PR
435214	WELL	PR	10/01/2020	OW	123-38508	Razor 22D-2703A	PR
435216	WELL	SI	12/01/2021	OW	123-38510	Razor 22D-2207A	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Wellheads; see photos		
Corrective Action:	Comply with Rule 606	Date:	03/25/2022
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers on West and North sides of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	03/25/2022
Type	OTHER		
Comment:	Stained Soil at 2207 Wellhead, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	04/06/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts at 2208 and 2703A Wellhead; see photos		
Corrective Action:	Comply with Rule 606	Date:	04/22/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		

Comment: Barbed Wire					
Corrective Action:				Date:	
Equipment:				corrective date	
Type: LACT		# 2			
Comment:					
Corrective Action:				Date:	
Type: Emission Control Device		# 1			
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run		# 8			
Comment:					
Corrective Action:				Date:	
Type: Horizontal Separator		# 1			
Comment:					
Corrective Action:				Date:	
Type: Flare		# 1			
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift		# 4			
Comment:					
Corrective Action:				Date:	
Type: VRU		# 1			
Comment:					
Corrective Action:				Date:	
Type: Vertical Separator		# 2			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead		# 4			
Comment: Appear to be plumbed to surface					
Corrective Action:				Date:	
Type: Vertical Heater Treater		# 2			
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	200 BBLS	STEEL AST		40.829770,-103.857660	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	18	400 BBLs	STEEL AST		40.830230,-103.859250
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type	Field Flare		
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 430694 Type: WELL API Number: 123-36257 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 435213 Type: WELL API Number: 123-38507 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 435214 Type: WELL API Number: 123-38508 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 435216 Type: WELL API Number: 123-38510 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder:

Comment: SI

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection.	petrie	03/21/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402991342	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700382
696304059	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5700380