

# Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 3/29/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/29/2022

## Inspection Photos



**Photo 1.** Facing southwest along the main road in the canyon. The road has been graded however, there is still culvert maintenance needed. Red arrow points to erosion undercutting by the culvert which will end up eroding the culvert outlet.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/29/2022

## Inspection Photos



**Photo 2.** Facing west toward the access road ascending the hillside. The road has been graded. The culvert inlet shown at red arrow and the outlet is shown in photo 4.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/29/2022

## Inspection Photos



**Photo 3.** The culvert outlet is eroded and does not have outlet protection. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/29/2022

## Inspection Photos



**Photo 4.** Facing southwest toward the location. The well site was not inspected. This photo was taken from prior inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07915 | Date: 3/29/2022