

Caerus Piceance LLC
K33NW
Location # 334632



Location/ lack of battery signage



location



Caerus Piceance LLC
K33NW
Location # 334632



Location



Staining



Caerus Piceance LLC
K33NW
Location # 334632



Open ended pipe



Open ended pipe and debris



Caerus Piceance LLC
K33NW
Location # 334632



Cut slope show some areas of erosion



Cut slope show some areas of erosion

Caerus Piceance LLC
K33NW
Location # 334632



Lack of stabilization/compaction



Lack of stabilization/compaction

