

TEP
KP 32-17
Location # 335239



location



location

TEP
KP 32-17
Location # 335239



location



Lack of stabilization/ compaction/ degradation



TEP
KP 32-17
Location # 335239



Lack of stabilization/ compaction/ degradation



Lack of stabilization/ compaction/ degradation



TEP
KP 32-17
Location # 335239



Lack of stabilization/ compaction/ degradation



Lack of stabilization/ compaction/ degradation



TEP
KP 32-17
Location # 335239



Valve missing cap/plug under water



Valve missing cap/plug



TEP
KP 32-17
Location # 335239



Debris



Debris

TEP
KP 32-17
Location # 335239



Debris



Cut slope erosion/ lack of stabilization



TEP
KP 32-17
Location # 335239



Cut slope erosion/ lack of stabilization



Cut slope erosion/ lack of stabilization

TEP
KP 32-17
Location # 335239



Cut slope erosion



Main access road shows signs of degradation

