

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2022

Submitted Date:

03/29/2022

Document Number:

688801126

FIELD INSPECTION FORMLoc ID 333495 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com	All Inspections SW
Fischer, Alex		alex.fischer@state.co.us	
Killough, Mitch		mkillough@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216561	WELL	PR	11/27/2007	GW	067-08167	FLORIDA RIVER ESTATES 33-9 20-1	EI
289932	WELL	PR	02/01/2011	GW	067-09340	FLORIDA RIVER ESTATES 33-9 20-1A	EI

General Comment:

On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company Florida River Estates 33-9 #20-1. For the most recent field inspection report of this facility, please refer to document #693902376.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing signs near each well head.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil	WELLHEAD	<= 1 bbl		
Comment:	Well head and surrounding gravel are stained at the #20-1.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 04/29/2022

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe barricade fencing around both well heads.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing present on both pump jacks.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Valve can.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Electric motors.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>216561</u>	Type:	<u>WELL</u>	API Number:	<u>067-08167</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>289932</u>	Type:	<u>WELL</u>	API Number:	<u>067-09340</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company Florida River Estates 33-9 #20-1. For the most recent field inspection report of this facility, please refer to document #693902376. During this inspection staining was observed on and around the #20-1 well head.	hughesjo	03/29/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402997673	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706910
688801127	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706906