

Inspection Photos

API: 071-06723

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 2. Facing southeast along the road. There are signs of erosion in this area of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 3. Facing southeast toward the location standing above the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 4. Facing toward the cut slope. There are signs of erosion along the cut slope which is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 5. Facing west at the location. The location has not been recontoured and vegetation has not established in areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 6. Facing south at the location.



Inspection Photos



Photo 7. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 8. Facing southeast toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022

Inspection Photos



Photo 9. There is a exposed black poly line at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 4/4/2022