

Inspection Photos
E. Stieber Consolidation
Facility IDs: 480275 & 481906



Photo 1 – April 5, 2022 – Initial spill response to new spill; liquids removal



Photo 2 – April 5, 2022 – New spill



Inspection Photos
E. Stieber Consolidation
Facility IDs: 480275 & 481906



Photo 3 – April 5, 2022 – Initial spill response to new spill: Exposed damaged flowline



Photo 4 – April 5, 2022 – Initial spill response to new spill: Hydrovac



Inspection Photos
E. Stieber Consolidation
Facility IDs: 480275 & 481906



Photo 5 – April 5, 2022 – Initial spill response to new spill



Photo 6 – April 5, 2022 – Initial spill response to new spill



Inspection Photos
E. Stieber Consolidation
Facility IDs: 480275 & 481906



Photo 7 – April 5, 2022 – Improper installation of BMPs



Photo 8 – April 5, 2022 – Stockpiled soil with inadequate BMPs



Inspection Photos
E. Stieber Consolidation
Facility IDs: 480275 & 481906



Photo 9 – April 7, 2022 – Fencing and exposed flowline



Photo 10 – April 7, 2022 – Exposed flowline



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources