

Caerus Piceance LLC
K17E
Location # 334791



Location



location

Caerus Piceance LLC
K17E
Location # 334791



Location



Some areas of lack of stabilization/compaction



Caerus Piceance LLC
K17E
Location # 334791



Erosion



Erosion



Caerus Piceance LLC
K17E
Location # 334791



Sediment migration




Erosion



Caerus Piceance LLC
K17E
Location # 334791



Cap on burner not installed and burner is running



Cap on burner not installed, burner is not running.