

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

702000158**FIELD INSPECTION FORM**Loc ID 312968 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223072	WELL	PR	08/26/1981	GW	081-06434	POWDER WASH FEDERAL 28-3	PR

General Comment:

Routine follow up inspection. Follow up to inspection from 1/3/2022 document number 689806877 and 11/16/2020 document number 689804996. No corrective actions appear to have been made. Compliance issues remaining:

tank labels missing

no pit permits on file for 2 pits on location

Compliance issues observed during this inspection:

stained soil at pump jack exhaust

landfarm area

no freeboard in pit in tank battery

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tanks missing labels or with incomplete labels.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/20/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at pump jack exhaust.		
Corrective Action:	Comply with Rule 606 Properly dispose of oily waste in accordance with 905.e.	Date:	05/12/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	223072	Type:	WELL	API Number:	081-06434	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement.								
Corrective Action:	Submit required Form 7(s) to COGCC per rule 413.						Date:	05/12/2022	

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)		
Oily Soil	Land Treatment	Inadequate	40.889924	-108.298957	
Comment		Fenced landfarm area.			
Corrective Action					Date:

Spill/Remediation:

Comment:			
Corrective Action:			Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: YES

2+ feet Freeboard: NO

Comment:

Two pit ids with this location 100421, 100424. No pit permit on file. Less than 2-feet of freeboard in pit in tank battery.

Corrective
Action

Lower fluid level so at least two feet of freeboard exists per Rule 909.c.
Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 908.a.

Date: 04/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702000163	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721482