

TEP
Overacker 20-13B
Location # 335139



location



location

TEP
Overacker 20-13B
Location # 335139



location



location and debris

TEP
Overacker 20-13B
Location # 335139



Stored vehicles/ trailers and debris



Debris

TEP
Overacker 20-13B
Location # 335139



Stored vehicles/ trailers



**Cut slope shows signs of lack of stabilization/
erosion**



TEP
Overacker 20-13B
Location # 335139



**Cut slope shows signs of lack of stabilization/
erosion**



Staining

TEP
Overacker 20-13B
Location # 335139



Truck loading fluids from valve on tank. Operator considers this valve is NOT used as a line to load trucks with fluid. Truck was actively loading fluid at time of inspection.

