

Inspection Photos
Operator: Simcoe
API: 067-07787
Date: 4/8/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, smooth brome, and sleepy grass.



Photo 3. View of unknown riser within the northern project area.



Photo 4. View of the western project area from the southwestern corner facing northward.



Photo 5. View of musk thistle rosettes within the northwestern portion of the interim reclamation area.



Photo 6. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, James galleta, western wheatgrass, and sandberg bluegrass.