

Inspection Photos
Operator: Simcoe
API: 067-07030
Date: 4/8/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southeastern project area from the eastern corner facing southwestward. Revegetation is progressing with western wheatgrass and smooth brome.



Photo 3. View of the southwestern project area from the southern corner facing northwestward.



Photo 4. View of reference area comprised of ponderosa pine woodland with black sagebrush, gambel oak, James galleta, Oregon grape, and fringed sage in the understory.