

Inspection Photos
Operator: Simcoe
API: 067-08806
Date: 4/19/2022



Photo 1. View of the project area from the southwestern corner facing center. BMPs are needed where concentrated stormwater flows of the southwestern corner of the project area.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with fourwing saltbush, rubber rabbitbrush, crested wheatgrass, sand dropseed, western wheatgrass and smooth brome.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of headcut erosion observed at the edge of the southwestern corner of the project area; approx 2-3ft wide and deep.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, western wheatgrass, James galleta, and yellow milkvetch.