

Inspection Photos

API: 071-08083

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 1. Facing southeast along the main access road. The black poly line remains exposed to potential damage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 2. The damaged culvert debris needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 3. Facing south along the main road. The bank of the stream crossing needs to be stabilized. The cement culvert outlet should be reinstalled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 4. The cement culvert is filled in with sediment. The culvert at red arrow is not sufficient as shown by the size of the previous culvert. The liner debris in lower portion of photo needs to be removed. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 5. There is a produced water line that is bent over on the ground at the stream drainage which needs to be repaired. Previous corrective action was not completed. Photo taken from previous inspection but is also shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 6. There is another produced water line that is bent over on the ground at the next crossing which needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08083 | Date: 4/19/2022

Inspection Photos



Photo 7. Facing toward the well site.

