

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2022

Submitted Date:

04/20/2022

Document Number:

699503873

**FIELD INSPECTION FORM**

Loc ID 318935 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 52060  
Name of Operator: M E III CORPORATION  
Address: 2670 PIERCE ST  
City: WHEAT RIDGE State: CO Zip: 80214

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
		sernest1@hotmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242533	WELL	SI	09/01/2020	GW	123-10324	PERRY 3	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Mechanical issue with grease zerk on midstream equipment see pic 5,6, Stained soil, some weed growth on location		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	06/20/2021

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	fabricated fencing around wellhead and midstream equipment		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST			
Comment:	80 BBL					
Corrective Action:					Date:	

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:	shares containment with oil tank					
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 242533 Type: WELL API Number: 123-10324 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Date: 05/30/2021

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 4/19/22 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Perry 3                      Company Name- M E III                      API- 05-123-10234                      In Weld County Colorado.                      While there, I observed SI well                      This is a follow up inspection from document # 699502774 &amp; Warning letter Document # 402359814 &amp; 402493112 Corrective Actions are Delinquent                      During this inspection the following possible compliance issues were observed:                      Mechanical issue with grease zerk on midstream equipment. Stained soil below leaking grease zerk. Some weed growth on location                      Comply with COGCC housekeeping rules 6/20/21                      No annual bradenhead test on file. Contact COGCC engineering. Provide Monthly monitoring data                      Comply with COGCC annual bradenhead testing rules. 5/30/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This inspection does not nullify any orders or NOAV from the COGCC.                      This is a summary of inspection report.</p>	medinaj	04/20/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503874	Inspection Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729288">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729288</a>