

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2022

Submitted Date:

04/15/2022

Document Number:

700704103

## FIELD INSPECTION FORM

 Loc ID 334693 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Operator Information:**
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 18 Number of Comments  
 4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285600	WELL	PR	06/14/2010	GW	045-12525	COUEY 24-6 (F24W)	PR
285601	WELL	PR	09/01/2018	GW	045-12524	COUEY FEDERAL 24-3 (F24W)	PR
285602	WELL	PR	07/15/2007	GW	045-12523	COUEY FEDERAL 24-3D (F24W)	PR
293065	WELL	PR	02/01/2011	GW	045-14862	COUEY 24-7 (F24W)	PR
293066	WELL	PR	01/01/2011	GW	045-14863	COUEY 24-10B (F24W)	PR
293067	WELL	PR	09/21/2008	GW	045-14864	COUEY 24-10 (F24W)	PR
293068	WELL	PR	02/01/2011	GW	045-14865	COUEY 24-11 (F24W)	PR
293159	WELL	PR	02/01/2011	GW	045-14907	COUEY 24-2D (F24W)	PR
293394	WELL	SI	10/01/2020	GW	045-14954	COUEY 24-6D (F24W)	SI

**General Comment:**

COGCC Inspection Report Summary

On Thursday 4/15/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus F24W, at Location # 334693 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Some of the access and location shows signs of lack of stabilization/ compaction/ degradation.
2. Valve on tank missing cap/plug.
3. Lack of battery signage.
4. Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	See storm water	
	Corrective Action	L	Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.	
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:	Lack of battery signage.	
	Corrective Action:	Provide proper signage	Date: <u>07/08/2022</u>
	Type	CONTAINERS	
	Comment:		
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:

<b>Emergency Contact Number:</b>			
	Comment:	911	
	Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
	Type	OTHER	
	Comment:	Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.	
	Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.	Date: <u>04/29/2022</u>
	Type	OTHER	
	Comment:	Valve on tank missing cap/plug.	
	Corrective Action:	Install cap/plug	Date: <u>06/03/2022</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	285600	Type:	WELL	API Number:	045-12525	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	285601	Type:	WELL	API Number:	045-12524	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	285602	Type:	WELL	API Number:	045-12523	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293065	Type:	WELL	API Number:	045-14862	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293066	Type:	WELL	API Number:	045-14863	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293067	Type:	WELL	API Number:	045-14864	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293068	Type:	WELL	API Number:	045-14865	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293159	Type:	WELL	API Number:	045-14907	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 293394 Type: WELL API Number: 045-14954 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Compaction	Fail			

Comment: 1. Some of the access and location shows signs of lack of stabilization/ compaction/ degradation.

Corrective Action: Install or repair required BMPs

Date: 06/03/2022

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403017368	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725301">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725301</a>
700704112	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725289">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725289</a>