

Inspection Photos

Location Name: Elton N Miller 2

Location ID: 318286



Pic 1 wellhead / pump jack



Pic 2 leaking gear oil/stained soil/mechanical issue.