

# Inspection Photos

April 18 and April 21, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334901

Location Name: Shideler-66S92W /32SWNE

Inspection Document #: 702800144

Garfield County, CO

SWNE Section 32 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901

4/18/22  
+39.486043,-107.689858



**Photo 1.** Photo taken from the west of the Location facing northeast shows an overview of the Location. Note: due to GPS malfunction, GPS coordinates for this photo are incorrect.





Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



**Photo 2.** Photo taken from the interim area to the north of the Location facing east shows the interim area dominated by bare ground. Note GPS coordinates for this photo are incorrect, due to GPS malfunction.



**Photo 3.** Photo taken from the interim area to the west of the Location facing southeast shows the interim area dominated by bare ground and the undesirable plant species/weed kochia. Note GPS coordinates for this photo are incorrect, due to GPS malfunction.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



4/21/22  
+39.486555,-107.688438

**Photo 4.** Photo taken from the interim area to the north of the Location facing east shows erosion occurring in interim areas dominated by bare ground. Shrubs present do not appear sufficient to stabilize soils.



4/21/22  
+39.486588,-107.687898

**Photo 5.** Photo taken from the interim area to the east of the Location shows the interim area dominated by bare ground and annual undesirable plant species/weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800144



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



**Photo 6.** Photo taken from the north of the Location shows a gully developing on Location.



**Photo 7.** Photo taken from the north of the Location shows a gully developing on Location and leading into the adjacent property.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



**Photo 8.** Photo taken from the north of the Location facing south shows erosion occurring in unvegetated/unstabilized interim areas.



**Photo 9.** Refer to Photo 8 comment.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



**Photo 10.** Photo taken from the north of the Location shows a gully developing on Location and leading into the adjacent property.



**Photo 11.** Refer to Photo 10 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800144



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



**Photo 12.** Photo taken from the east of the Location behind the separator. Photo is taken on the inside of the undermining berm where sediment is leaving the production area.



**Photo 13.** Photo taken from the east of the Location behind the separator. Photo is taken on the outside of the undermining berm where sediment is coming through.



Inspection Photos  
Location Name: Shideler-66S92W /32SWNE  
Location ID: 334901



**Photo 14.** Photo taken from the east of the Location behind the separator shows the berm undermining. Sediment is coming through the berm.

