

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2022

Submitted Date:

04/19/2022

Document Number:

696304127

**FIELD INSPECTION FORM**

Loc ID 318871 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 30560  
Name of Operator: FORTITUDE EXPLORATION CO  
Address: P O BOX 5417  
City: NAVARRE State: FL Zip: 32566

**Findings:**

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Culek, Joe		j.culek@charter.net	
Dillon, Gregory		gregory_dillon@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242350	WELL	TA	11/01/2021	OW	123-10141	U S A 21-6	PR

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	West Tank missing all Labels - NFPA, Content and Capacity; See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/20/2022
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Unused part to Tank Walk by Pit Area and Unused Vavle at Tank Berm; see photos		
Corrective Action:	Comply with Rule 606	Date:	05/20/2022

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.962370,-103.687080
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 242350 Type: WELL API Number: 123-10141 Status: TA Insp. Status: PR

**Producing Well**

Comment: [PR - Wellhead Producing at the time of this Inspection](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat: <u>40.962040</u>	Long: <u>-103.687000</u>		
Reference Point: <u>SE</u>	Other: _____	Length: <u>30</u>	Width: <u>30</u>			
<b>Lining:</b>						
Liner Type:			Liner Condition:			
Comment: <input style="width:95%;" type="text"/>						Date:
Corrective Action: <input style="width:95%;" type="text"/>						Date:
<b>Fencing:</b>						
Fencing Type: <u>Safety</u>			Fencing Condition: <u>Inadequate</u>			
Comment: <u>SW Corner of Pit Fence is in Disrepair; see photos</u>						Date:
Corrective Action: <u>Install or repair wildlife protection equipment. Per Rule 608.a.(13)</u>						Date:
<b>Netting:</b>						
Netting Type:			Netting Condition:			
Comment: <input style="width:95%;" type="text"/>						Date:
Corrective Action: <input style="width:95%;" type="text"/>						Date:
Anchor Trench Present:		Oil Accumulation: <u>NO</u>		2+ feet Freeboard: <u>YES</u>		
Comment: <input style="width:95%;" type="text"/>						Date:
Corrective Action: <input style="width:95%;" type="text"/>						Date:

COGCC Comments		
Comment	User	Date
<a href="#">Routine Field Inspection. West Tank missing Labels: NFPA, Content and Capacity. Unused Valve and Cat Walk</a>	petrie	04/19/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403020294	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5727463">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5727463</a>
696304128	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5727460">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5727460</a>