

Inspection Photos
Operator: Simcoe
API: 067-07138
Date: 4/26/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of straw blankets on the well pad cut-slope no longer functioning.



Photo 5. View of the reference area comprised of ponderosa pine forest with gambel oak (*Quercus gambelii*), Oregon grape (*Mahonia repens*), and Idaho fescue (*Festuca idahoensis*).