

# Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 4/25/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022

## Inspection Photos



**Photo 1.** Facing north along the access road which has not been recontoured and reclaimed. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022

## Inspection Photos



**Photo 2.** Facing northwest toward the former tank battery site located 300' southwest of the well site. The access road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 3.** Facing northwest toward the former tank battery site located 300' southwest of the well site. This area has not been reclaimed. The electric fence was repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 4.** There is a pipe riser near the tank battery has been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022

## Inspection Photos



**Photo 5.** There are two pipes that remain at the battery site that need to be removed. Also a T-Post.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 6.** Facing southwest toward the abandoned battery site. This area has not been reclaimed. The electric fence was repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022

## Inspection Photos



**Photo 7.** Facing northeast toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 8.** Facing south toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022

## Inspection Photos



**Photo 9.** The other abandoned risers have been removed at north side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 10.** Drone aerial photo facing north along the access road toward the location. The red arrow points to the former tank battery site and yellow arrow points to the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 11.** Facing northeast toward the tank battery site and well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022



## Inspection Photos



**Photo 12.** Facing back south toward the well site. The red arrow points to the former tank battery site and yellow arrow points to the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05138 | Date: 4/25/2022