

Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647



Photo#1 Production Tanks



Photo#2 Vertical Separator

Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647



Photo#3 Produced Water Open Top Tank/Hydrocarbons in water. Open top tank is venting gas.



Photo#4 Large gaps under both production tanks



Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647



Photo#5 Large gaps under both production tanks



Photo#6 Large gaps under both production tanks

Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647



Photo#7 No Bullplug/Stained Soil



Photo#8 Large gaps under both production tanks



Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647



Photo#9 Large gaps under both production tanks



Photo#10 Large gaps under both production tanks

Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647




Photo#11 Small leak on north tank



Photo#12 Debris/Unused Equipment

Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647




Photo#13 Small leak



Photo#14 Pumpjack



Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647




Photo#15 Wellhead leaking



Photo#16 Wellhead leaking

Inspection Photos
Location Name: Holmquist UPRR 1-1
Location ID:319647



Photo#17 Stained Soil



Photo#18 Bucket needs emptied

