

Inspection Photos
Location Name: Sack G Unit
Location: 320295, API: 05-001-08895



Open Excavation with inadequate safety fencing.



Spoils pile, and debris from cutting and capping the Sack G Unit 1, with inadequate stormwater BMPs.

Inspection Photos
Location Name: Sack G Unit
Location: 320295, API: 05-001-08895



1 of 5 unlabeled zip lock bags of what is assumed to be investigation-derived waste.



1 of 5 unlabeled zip lock bags of what is assumed to be investigation-derived waste.

Inspection Photos
Location Name: Sack G Unit
Location: 320295, API: 05-001-08895



Top of former concrete partially buried vessel on the ground next to an open excavation in which the operator has placed non-E&P waste, specifically, broken pieces of the concrete vessel.



Concrete partially buried vessel, broken into pieces which were placed in an open excavation.

Inspection Photos
Location Name: Sack G Unit
Location: 320295, API: 05-001-08895



Concrete partially buried vessel, broken into pieces which were placed in an open excavation.



Concrete partially buried vessel, broken into pieces which were placed in an open excavation.

Inspection Photos
Location Name: Sack G Unit
Location: 320295, API: 05-001-08895



Sack G Unit 1 after being cut and capped.



Sections of flowline being staged on location.