

Inspection Photos
facility ID 427371, REM 17852
427370, REM 17848
286608, REM 17854
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel



Photo #1, upper pit facility 427371. The anchor trench portion of the liner is still in ground. All liner must be removed, including the anchor trench. Some water was present in pit, No obvious hydrocarbon or salt impacts were observed.



Inspection Photos
facility ID 427371, REM 17852
427370, REM 17848
286608, REM 17854
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #2, upper pit, facility 427371. The anchor trench portion of the liner is still in ground. All liner must be removed, including the anchor trench.

Inspection Photos
facility ID 427371, REM 17852
427370, REM 17848
286608, REM 17854
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel



Photo #3 Middle Pit, Facility 427370. The anchor trench portion of the liner is still in ground. All liner must be removed, including the anchor trench.

Inspection Photos
facility ID 427371, REM 17852
427370, REM 17848
286608, REM 17854
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel



Photo #4 Facility 286608



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
facility ID 427371, REM 17852
427370, REM 17848
286608, REM 17854
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #5 lower Pit, No liner appeared to be present. Facility 286608.

Inspection Photos
facility ID 427371, REM 17852
427370, REM 17848
286608, REM 17854
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel



Photo #6 Large Pit, facility 427372, August 2022 is expected date of closure, per SWN meeting 4/26/22.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources