

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



Photo #6582 from entrance to location.



Photo #6583 from entrance to location.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



**Photo #6584** Location lacks stabilization.



**Photo #6585** Location lacks stabilization.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHORE-67S95W /16SWNE

Location ID: 334599



**Photo #6586 Insufficient tracking BMP at entrance to location.**