

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2022

Submitted Date:

05/02/2022

Document Number:

696304150

FIELD INSPECTION FORMLoc ID 440372 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jenkins, Steve		steve.jenkins@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440371	WELL	PR	08/01/2020	OW	123-40813	HESTON LD06-625	PR
440374	WELL	PR	08/01/2020	OW	123-40815	HESTON LD06-630	PR
440375	WELL	SI	09/01/2021	OW	123-40816	HESTON LD06-620	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Chemical Tank on West end of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	06/03/2022
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at 620 Wellhead; see photos		
Corrective Action:	Comply with Rule Rule	Date:	05/06/2022
Type	STORAGE OF SUPL		
Comment:	Unused Walkover Stand on South end of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	06/03/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire Fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 440371 Type: WELL API Number: 123-40813 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 440374 Type: WELL API Number: 123-40815 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 440375 Type: WELL API Number: 123-40816 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily Abandoned

Reminder:

Comment: Well appears to be Plugged and Abandoned per Form 42 Notice of Plugging 402947560 with a Start Date of 02.08.2022.
No Form 6 S (Subsequential) appears to be on File.

Corrective Action:

Within 30 days after abandonment, the Form 6, Well Abandonment Report – Subsequent Report of Abandonment will be filed with the Director.

Date: 05/06/2022**COGCC Comments**

Comment

User

Date

Routine Field Inspection. Unused Chemical Container on West end of Location. Unused Walkover Stand on South end of Location. Unmarked Risers at 620 Wellsite. 620 Well appears to be Plugged and Abandoned - no Form 6S on File

petrie

05/02/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304151	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5741398