

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2022

Submitted Date:

05/02/2022

Document Number:

696304152**FIELD INSPECTION FORM**Loc ID 440372 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440371	WELL	PR	08/01/2020	OW	123-40813	HESTON LD06-625	PR
440374	WELL	PR	08/01/2020	OW	123-40815	HESTON LD06-630	PR
440375	WELL	SI	09/01/2021	OW	123-40816	HESTON LD06-620	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Pipe Stands and Tarp on West side of Location, see photos		
Corrective Action:	Comply with Rule 606	Date:	06/03/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire Fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: VRU	# 3		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: LACT	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	#		
Comment:	24		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Instrumental Air Unit		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	FIBERGLASS AST		40.631280,-104.000890	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.769680,-103.901070	
Comment:				Maintenance Tank		
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	500 BBLs	STEEL AST		40.771050,-103.901390	
Comment:						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 440371 Type: WELL API Number: 123-40813 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: Facility ID: 440374 Type: WELL API Number: 123-40815 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: Facility ID: 440375 Type: WELL API Number: 123-40816 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Unused pipe stands and Tarps on the West side of location	petrie	05/02/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304153	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5741399