

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2022

Submitted Date:

04/26/2022

Document Number:

691201596

## FIELD INSPECTION FORM

 Loc ID 335736 Inspector Name: Graber, Candice (Nikki) On-Site Inspection  2A Doc Num:
**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

 Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Rickard, Jeff		JRickard@kpk.com	KPK environmental
Gorka, Ray		RGorka@kpk.com	KPK environmental
, KPK		cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272093	WELL	PR	11/01/2021	OW	001-09503	SACK 7-11	EI
476379	OFF-LOCATION FLOWLINE	AC	03/31/2022		-	Wellhead Line 2-X	EI
476380	OFF-LOCATION FLOWLINE	AC	03/31/2022		-	Wellhead Line 2-X	EI

**General Comment:**

This is an environmental inspection any corrective actions from previous inspections that have not been addressed are still applicable.  
Photos attached to document site conditions.

**Inspected Facilities**

Facility ID: 272093 Type: WELL API Number: 001-09503 Status: PR Insp. Status: EI

Facility ID: 476379 Type: OFF- API Number: - Status: AC Insp. Status: EI

Facility ID: 476380 Type: OFF- API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Approximately 8 cubic yards of impacted soils were stockpiled on a liner.

Corrective Action: Supplemental Form 27 shall include volume of impacted soils removed and waste manifests; if impacts trigger a Spill/Release Report operator shall submit a Form 19 in accordance with Rule 912. Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: COGCC inspectors observed activities related to tank battery dismantlement, wellhead P&A at two off location wellheads, and flowline abandonment at this location. At the time of inspection crews were removing the tank battery and an excavation was present around the wellheads; the off location flowline was not exposed while inspectors were present.

Operator was conducting work without an approved Form 27 workplan. Per Rule 911.a.(1) "Operators will obtain the Director's approval of the Form 27 prior to conducting any investigation or closure operations."

Corrective Action: No corrective action date is provided as Operator is out of compliance with Rule 911.a.(1) . Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403028040	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735534">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735534</a>
691201597	Excavation Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735526">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735526</a>
691201598	Excavation Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735527">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735527</a>
691201599	Wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735528">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735528</a>
691201600	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735529">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735529</a>
691201601	Soils stockpile	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735530">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735530</a>