

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2022

Submitted Date:

04/26/2022

Document Number:

691201602**FIELD INSPECTION FORM**Loc ID 320509 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone | Email            | Comment           |
|---------------|-------|------------------|-------------------|
| Rickard, Jeff |       | JRickard@kpk.com | KPK environmental |
| , KPK         |       | cogcc@kpk.com    | All Inspections   |
| Gorka, Ray    |       | RGorka@kpk.com   | KPK environmental |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 272094      | WELL | PR     | 11/01/2021  | OW         | 001-09504 | SACK 8-11     | EI          |

**General Comment:**

This is an environmental inspection any corrective actions from previous inspections that have not been addressed are still applicable.  
Photos attached to document site conditions.



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Non observed, KPK personnel were screening the excavation at time of inspection.

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: COGCC inspectors observed activities related to wellhead P&A and flowline abandonment at this location. At the time of inspection KPK personnel were screening the excavation; the off location flowline was not exposed while inspectors were present.

Operator was conducting work without an approved Form 27 workplan. Per Rule 911.a.(1) "Operators will obtain the Director's approval of the Form 27 prior to conducting any investigation or closure operations."

Corrective Action: No corrective action date is provided as Operator is out of compliance with Rule 911.a.(1) . Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description            | URL   |
|--------------|------------------------|---|
| 403028041    | INSPECTION SUBMITTED   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735535">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735535</a> |
| 691201603    | Excavation at wellhead | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735531">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5735531</a> |