

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2022

Submitted Date:

05/04/2022

Document Number:

700901115

**FIELD INSPECTION FORM**

Loc ID 319714 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Findings:**

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>
		dnr_cogccenforcement@state.co.us	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201072	WELL	PR	10/01/2020	OG	001-06475	FERGUSON 2-25	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	605.d. Signs and Markers on Pump Jack.		
Corrective Action:	Corrective Action Date 6/8/2022. See attached photo # 10.	Date:	07/06/2022

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	TRASH		
Comment:	Rule 606.(Trash used plastic buckets in separator house).		
Corrective Action:	Corrective Action Date 5/25/2022. See attached photos # 4 & 5	Date:	05/25/2022

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:			corrective date
Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment: Rule 603.o.(1) Inadequate / unmaintained berms around tank(s) (base under Produced water tank)				
Corrective Action: Corrective Action Date 6/8/2022. See attached photo # 7.				Date: 06/08/2022

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		39.847863,-104.274360
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
001-06499
001-08792
001-06482
001-06475
001-06501
001-06513
001-06523

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 201072 Type: WELL API Number: 001-06475 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<u>PR</u>	
Corrective Action:		Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><u>COGCC Inspection Report Summary</u>  <u>On Wednesday May 4, 2022 at approximately 9:45am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.</u>  <u>Operator: RENEGADE OIL &amp; GAS</u>  <u>Well Name: Ferguson 2-25</u>  <u>API #: 001-06475</u>  <u>Location ID#: 319714</u>  <u>County: Adams</u>  <u>While there, I observed a Producing well.</u>  <u>During this inspection the following possible compliance issues were observed:</u>  <u>Rule 603.o.(1) Inadequate / unmaintained berms around tank(s) (base under Produced water tank) Corrective Action Date 6/8/2022. See attached photo # 7.</u>  <u>Rule 606.(Trash used plastic buckets in separator house.) Corrective Action Date 5/25/2022. See attached photos # 4 &amp; 5.</u>  <u>Rule 909.d. Hydrocarbons observed on pit. Corrective Action Date 6/8/2022. See attached photo # 9.</u>  <u>Rule 605.d. Signs and Markers on Pump Jack. Corrective Action Date 6/8/2022. See attached photo # 10.</u></p> <p><u>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</u>  <u>This is a summary of inspection report.</u></p>	<u>finkenbc</u>	<u>05/04/2022</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>700901116</u>	<u>Inspection photos</u>	<u><a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745303">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745303</a></u>