

# Inspection Photos

API: 009-06236

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/6/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06236 | Date: 5/6/2022

## Inspection Photos



**Photo 1.** Facing northeast toward wellsite. Previous corrective action is not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 5/6/2022

## Inspection Photos



**Photo 2.** The tank on the location is busted apart and there is a solidified oily substance inside the tank which appears to have spilled out. Previous corrective action is not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 5/6/2022



## Inspection Photos



**Photo 3.** This photo shows the solidified oily substance inside the tank. Previous corrective action is not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 5/6/2022



## Inspection Photos



**Photo 4.** There is weed debris around the equipment which is a fire hazard. The well sign has fallen over and needs to be properly installed. The emergency contact number was not valid and does not meet the signage requirements. Previous corrective actions have not been completed.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 5/6/2022