

Inspection Photos

ID:438617

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 1. Facing northeast toward the gas treatment facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 2. There is an unused compressor stored on location that need to be removed. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 3. The facility sign is obscured behind the compressor. The emergency contact number is not valid. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 4. Facing toward the open top tank. It appears the tank has previously leaked due to white stained soil. There is no secondary containment around the tank. There is no signage on the tank. Previous corrective action is not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 5. The netting over the tank is not installed. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 6. There is equipment not maintained on location. Door has fallen off this shed. Previous corrective action is not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 7. There is oil/chemical containers and trash not properly or disposed of. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 8. There is an open top tank at the east side of the location. It appears the tank has previously leaked due to white stained soil. There is no secondary containment around the tank. The signage has faded. Previous corrective action is not completed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 9. The liquid in the tank is near the top which could spill over. The netting is not adequate to prevent wildlife entry. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 10. There is signs of a previous leak at the pipe fitting.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 11. There is unused supplies and a black barrels with no labeling. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022

Inspection Photos



Photo 12. Facing east toward the facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 5/6/2022